

RFP for Backup Tape Media Storage Vault

BRAC Bank PLC. is seeking a qualified and experienced vendor to provide secure offsite tape media vault (**Quantity-two**) for number of **200 tape** capacity with minimum five years of warranty to ensure our data protection and disaster recovery strategy and long-term data protection requirements.

1. RFP Specification for Backup Tape Media Storage Vault

Sl. No.	Feature	Minimum requirement	Compliance (Yes/No/Partial)	Response (Information should be validated with OEM product data sheet)
1	Brand	To be mentioned by the bidder		
2	Model	To be mentioned by the bidder		
3	Country of Origin	Should be mentioned by the bidder		
Key specifications				
4	Vault Construction	Walls, floor, and ceiling constructed with reinforced concrete or steel, minimum thickness 30 cm (12 inches) or as per structural engineering standards.		
		Vault must be completely windowless and sealed to prevent unauthorized entry or environmental ingress.		
		Vault door to be a heavy-duty, fire-rated steel door with tamper-proof locking mechanisms (e.g., UL 608 rated or equivalent).		
5	Structural Integrity	Designed to meet local building codes for structural stability, including earthquake and flood resistance if applicable		
		Vault must withstand external impacts, forced entry attempts, and environmental hazards such as flooding.		
6	Access Control	Mechanical security lock to prevent tailgating or unauthorized access.		
7	Climate Control	Temperature and humidity control: Temperature and humidity should be maintained within specific ranges, typically 20 degrees Celsius and 40% humidity inside the vault.		
8		Vault interior equipped with mechanical locked, reinforced steel shelving or cabinets for tape organization.		

Annexure_1: Technical Scope

Sl. No.	Feature	Minimum requirement	Compliance (Yes/No/Partial)	Response (Information should be validated with OEM product data sheet)
	Physical Security Measures	Anti-tamper seals or locks on tape containers or racks.		
9	Fire and Flood Protection (Structural)	Vault construction materials and design to be fire-resistant for a minimum of 6 hours per fire safety standards (e.g., UL 263).		
		Floor designed with water-resistant materials and a drainage system to prevent damage in case of flooding or water ingress.		
10	Warranty	Minimum of Five Years warranty		

** All information provided should be validated with supported document

Scope of Warranty and AMC Service:

The scope of service is as below but not limited to:

- Ensure that BRAC Bank can use all the vault's facilities as and when required.
- Faulty parts of the vault (i.e lock, door handle etc.) replacement within 4 hours
- All services and supplied parts, labor, transport, and logistic cost are included in the Warranty and AMC period.